

RQHR Laundry Services			BERSCH & ASSOCIATES LTD.													
			SAMPLE DATA													
Floor	Room Number	Use	SAMPLE SAMPLE REP	Sample ID	Date DD/MM/YY	Asbestos Type	% of Asbestos	Tradename ACM Product	Condition	Priority	Description of Sample Location	Asbestos Content In Area	Potential for Disturbance	Recommended Action	Comments	
M		Entry Corridor	Sample Rep.	B01-ASB.19	25-Feb-10	Chrysotile	30%	Asbestos Sheet Flooring	Mod/Good	3	Men's Locker Room - Sheet flooring, Two toned, tiny stone pattern	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Storage	Sample Rep.	B01-ASB.1	25-Feb-10	Chrysotile	40%	Transite Pipe	Good	4	Laundry Room (North) - Transite roof drain pipe running along the wall adjacent the receiving room, overhead height	Transite Pipe	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Receiving	Sample Rep.	B01-ASB.1	25-Feb-10	Chrysotile	40%	Transite Pipe	Good	4	Laundry Room (North) - Transite roof drain pipe running along the wall adjacent the receiving room, overhead height	Transite Pipe	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Laundry Room (North)	Sample	B01-ASB.1	25-Feb-10	Chrysotile	40%	Transite Pipe	Good	4	Laundry Room (North) - Transite roof drain pipe running along the wall adjacent the receiving room, overhead height	Transite Pipe	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Laundry Room (South)	Sample Rep.	B01-ASB.1	25-Feb-10	Chrysotile	40%	Transite Pipe	Poor/ Mod	1	Laundry Room (North) - Transite roof drain pipe running along the wall adjacent the receiving room, overhead height	Transite Pipe	Mod	Encapsulate	Annual inspection 2011 - No change in condition.	
M		Dryers area	Sample Rep.	B01-ASB.1	25-Feb-10	Chrysotile	40%	Transite Pipe	Good	4	Laundry Room (North)	Transite Pipe	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Staff Room	Sample Rep.	B01-ASB.1	25-Feb-10	Chrysotile	40%	Transite Pipe	Good	4	Laundry Room (North) - Transite roof drain pipe running along the wall adjacent the receiving room, overhead height	Transite Pipe above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Staff Room	Sample Rep.	B01-ASB.19	25-Feb-10	Chrysotile	30%	Asbestos Sheet Flooring	Mod/Good	3	Men's Locker Room - Sheet flooring, Two toned, tiny stone pattern	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Men's Locker Room	Sample	B01-ASB.19	25-Feb-10	Chrysotile	30%	Asbestos Sheet Flooring	Moderate	2	Men's Locker Room - Sheet flooring, Two toned, tiny stone pattern	Asbestos Sheet Flooring, Transite Pipe above suspended ceiling	Low/Mod	Manage	Annual inspection 2011 - No change in condition.	
M		Men's Locker Room	Sample Rep.	B01-ASB.1	25-Feb-10	Chrysotile	40%	Transite Pipe	Good	4	Laundry Room (North) - Transite roof drain pipe running along the wall adjacent the receiving room, overhead height	Asbestos Sheet Flooring, Transite Pipe above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Men's Washroom	Sample Rep.	B01-ASB.12	25-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Second floor Office - Sheet flooring, orange and cream coloured stone pattern	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Women's Washroom	Sample Rep.	B01-ASB.12	25-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Second floor Office - Sheet flooring, orange and cream coloured stone pattern	Asbestos Sheet Flooring	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Women's Locker Room	Sample Rep.	B01-ASB.1	25-Feb-10	Chrysotile	40%	Transite Pipe	Good	4	Laundry Room (North) - Transite roof drain pipe running along the wall adjacent the receiving room, overhead height	Asbestos Sheet Flooring, Transite Pipe above suspended ceiling	Low	Manage	Annual inspection 2011 - No change in condition.	
M		Women's Locker Room	Sample Rep.	B01-ASB.12	25-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Moderate	2	Second floor Office - Sheet flooring, orange and cream coloured stone pattern	Asbestos Sheet Flooring, Transite Pipe above suspended ceiling	Low/Mod	Repair/Remove	Annual inspection 2011 - No change in condition.	
M		First Aid Room	Sample Rep.	B01-ASB.12	25-Feb-10	Chrysotile	40%	Asbestos Sheet Flooring	Good	3	Second floor Office - Sheet flooring, orange and cream coloured stone pattern	Asbestos Sheet Flooring	Low	Remove	Annual inspection 2011 - No change in condition.	
M		South Laundry Washroom	Sample Rep.	B01-ASB.19	25-Feb-10	Chrysotile	30%	Asbestos Sheet Flooring	Poor	1	Men's Locker Room - Sheet flooring, Two toned, tiny stone pattern	Asbestos Sheet Flooring	Mod/High	Remove	Annual inspection 2011 - No change in condition.	

